



**ARMOR
AFTERMARKET**

Can Washer Vacuum Transfer Section Can Reject Section

The official post-sales division and parts supplier for Cincinnati Industrial Machinery

Recommended Spare Parts

| VACUUM TRANSFER | |
|----------------------------|----------------------|
| Part Description | Recommended Quantity |
| Vacuum Transfer Mat | 15 ft. |
| Gear Motor | 1 |
| Drive Shaft | 1 |
| Idle Shaft | 1 |
| Drive Sprockets | 4 |
| Idle Sprockets | 4 |
| Flange Bearings for Shafts | 2 |
| Vacuum Blower Motor | 1 |
| Pressure Transmitter | 1 |
| 2 Ton Jack Bolt | 1 |
| CAN REJECT | |
| Part Description | Recommended Quantity |
| Reject Mat | 17 ft. |
| Gear Motor | 1 |
| Drive Shaft | 1 |
| Idle Shaft | 1 |
| Tail Shaft | 1 |
| Drive Sprockets | 1 |
| Idle Sprockets | 4 |
| Flange Bearings for Shafts | 2 |

Note: These are recommended spare parts only. Parts, part numbers, and prices are subject to change without notice. Please contact Armor Aftermarket for questions, quotes, and service.

**Quantities represent the recommended spare parts only. Parts, part numbers, and prices are subject to change without notice. Some parts vary from model to model. Verify parts with Aftermarket representative at time of order. Please contact Armor Aftermarket for questions, quotes, and service.*



Contact us today

4600 N. Mason-Montgomery Road | Mason, OH 45040
513-923-5797 | partsandservice@Aftermarket.com

www.ArmorAftermarket.com

